



Date: 11/6/2020
Subject: Change to SAE/USCAR-17, Rev 5 (Letter #3)
To: Users of USCAR-17

This letter describes an immediate update to USCAR-17 section 4.4.2.2. Comments and/or questions should be addressed to EWCAP@uscar.org

Summary of changes:

- Eliminate steps 7 & 8 of 4.4.2.2.
- Adjust the test sequence for test groups O, Q, R, S, and T:
 - Change "connector cycling" to be step #3 (instead of step 4)
 - Change Initial VSWR and Insertion Loss to be step #4 (instead of step 3).

Reason a change is needed:

Current USCAR-17 has connector cycling listed in Table 5.3 and also as a step in 4.4.2. This results in connector cycling being done twice instead of the intended once. This applies to test groups O, Q, R, S, and T only.