

07/25/23

Subject: Change to USCAR-37, Rev 1 Letter #2

Changes have been made to USCAR-37, Rev 1 specification to update references to parts of USCAR-2 that have changed since USCAR-37 was last updated. Comments and questions can be sent to <u>EWCAP@uscar.org</u>.

This revision letter describes updates references on USCAR-37 to align with the latest version of USCAR-2.

CHANGES TO USCAR-37

Clause number	Reason for change	Change to:
5.7.1 Connector Mounting Feature Mechanical Strength	Clause number 5.7.1 is already used.	Change 5.7.1 to 5.7.2
5.8	Doesn't exist any longer in USCAR-2	Remove entire section.

SAE/USCAR-37 Issued 2008-08
HIGH VOLTAGE CONNECTOR PERFORMANCE SUPPLEMENT TO SAE/USCAR-2 - 21
5.7.2

5.7.1 Connector mounting feature mechanical strength.

See SAE/USCAR 2

5.8 Severe duty tests