

Date: 17 July, 2018

Subject: Change to SAE/USCAR-18, Rev 4 (Letter #3)

To: Users of USCAR-18

This letter describes two pending updates to SAE/USCAR-18.

- 1) Figure 3Y Female Contact is being updated to add clarity of the catch circle intent
- 2) Changing description in 3.2 Female Connector shown for reference only

Comments and/or questions should be addressed to EWCAP@uscar.org




Figure 3Y - Female Contact

Change #1

OLD





Figure 3Y - Female Contact

NEW

3.2 Female Connector

Must meet dimensions shown in Figure 3A and 3Y




Change #2

OLD

3.2 Female Connector Shown for Reference Only

Reference dimensions shown in Figure 3A and 3Y



NEW