



10/10/2022

Subject: Change to SAE/USCAR-2, Revision 8, (Letter #2)

Changes have been made to the USCAR-2 specification. Comments and questions can be sent to EWCAP@uscar.org.

Situation:

A reference in USCAR-2 was not updated when table numbers were changed.

Resolution:

The following is the corrected clause 5.4.1.4B:

The minimum retention force of a terminal from its cavity shall meet the values shown in the table 5.4.1.4B.