



12/06/2022

Subject: Change to SAE/USCAR-2, Revision 8, (Letter #4)

Changes have been made to the USCAR-2 specification. Comments and questions can be sent to EWCAP@uscar.org.

Situation:

A reference in a procedure has the incorrect reference number (12) in 5.6.6.3 #9. It currently says:

For Test Sequences Test Sequences S, RSAA, T, or TUAB (5.9.7), see Test Sequence for appropriate conditioning then proceed to step **12**. For Test Sequence W (5.9.9), proceed to next step.

Resolution:

The following change has been made to USCAR-2 5.6.6.3 Step 9 to correct to reference step 11.

“For Test Sequences Test Sequences S, RSAA, T, or TUAB (5.9.7), see Test Sequence for appropriate conditioning then proceed to step **11**. For Test Sequence W (5.9.9), proceed to next step.”