


04/19/2022

Subject: Change to SAE/USCAR-21, Rev 4 (Letter #5)

Changes have been made to the USCAR-21 specification. Figure 4.5.1.4, showing the 4-wire test probe set-up is more clear. Comments and questions can be sent to EWCAP@uscar.org.

Situation:

It was not clear which wires should be made of the thermocouple wire and which should be made of copper.



Resolution:

Redraw Figure 4.5.1.4 as shown.

